


# Schematic of Prototype IJAT



F161










FIG. 2



F16.3


# Guide Wire X-ray Alignment Jig







10/009915

# Magnet Insertion Tool



# IJAT Insertion Tool



SECTION A-A

TOOL HEAD VIEW  
4x SIZE

Fig. 7C

10/009915




FIG. 8





FIG. 9








FIG. 11




FIG. 13




FIG. 12




FIG. 14




FIG. 15